

2003/06/24 11.01
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_1731.html.Without corrections
0.04
0.02
0
-0.02
-0.04
-0.06
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_1747.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_1752.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system



2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_1753.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system



2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_1754.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system



2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r0_bs_1748.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p1_r1_bs_1695.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system



2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p2_r0_1729.html.Without corrections
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p2_r0_1744.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system



2003/06/24 11.02
afs.Wires_Coord_BOSXA_MPI_090_p2_r0_1746.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system

2003/06/24   11.02



Fluctuation of the wire vertical coordinates put in the same coord. system

2003/06/24   11.03



2003/06/24 11.03





2003/06/24 11.03
afs.Wires_Coord_BOSXA_MPI_090_p3_r0_1743.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
-0.05
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.03
afs.Wires_Coord_BOSXA_MPI_090_p4_r0_1712.html.Without corrections
0.02
0.01
0
-0.01
-0.02
-0.03
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.03
afs.Wires_Coord_BOSXA_MPI_090_p4_r0_1722.html.Without corrections
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system


2003/06/24 11.03
afs.Wires_Coord_BOSXA_MPI_090_p4_r0_1740.html.Without corrections
0.03
0.02
0.01
0
-0.01
-0.02
-0.03
-0.04
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system

2003/06/24 11.03

afs.Wires_Coord_BOSXA_MPI_090_p4_r0_bs_1682.html.Without corrections



Fluctuation of the wire vertical coordinates put in the same coord. system

2003/06/24 11.03




2003/06/24 11.03
afs.Wires_Coord_BOSXA_MPI_090_p5_r0_1727.html.Without corrections
0.02
0.01
0
-0.01
-0.02
-0.03
0
250
500
750
1000
1250
1500
1750
2000
Fluctuation of the wire vertical coordinates put in the same coord. system